



3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Page 1 of 2

Inspection report

Permittee/Operator Name Co-Op Mining Company
 Business Address P.O. Box 1245
 City Huntington State Ut Zip 84528
 Mine Bear Cyn Surface Underground Other
 County Emery State Ut
 Company Official(s) Gerald Hansen
 State Official(s) Bill Molenak
 Time of inspection 10:30 a.m. a.m. p.m. to 1:00 p.m. a.m. p.m. Partial Complete
 Date of last inspection 8/22/89 Weather conditions Clear/Sunny/Cool.
 Acreage 1060 Permitted 10 Disturbed Regraded Seeded 10 Bonded
 Enforcement Action _____

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

YES NO N/A COMMENTS

YES NO N/A COMMENTS

- | | | | | | | | | |
|---|-------------------------------------|-------------------------------------|--------------------------|-------------------------------------|---|-------------------------------------|--------------------------|-------------------------------------|
| 1. Permits | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | 9. Protection of fish, wildlife, and related environmental values | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Signs and markers | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | 10. Slides and other damage | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Topsoil | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | 11. Contemporaneous reclamation | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4. Hydrologic balance | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | 12. Backfilling and grading | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| – Stream channel diversions | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | 13. Revegetation | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| – Diversions | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | 14. Subsidence control | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| – Sediment ponds and impoundments | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | 15. Cessation of operations | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| – Other sediment control measures | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | 16. Roads | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| – Surface and groundwater monitoring | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | – Construction | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| – Effluent limitations | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | – Drainage controls | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 5. Explosives | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | – Surfacing | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 6. Development waste and spoil disposal | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | – Maintenance | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| 7. Coal processing waste | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | 17. Other transportation facilities | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| 8. Noncoal waste | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | 18. Support facilities and utility installations | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

INSPECTION REPORT COMMENTS

Permit No. ACT/015/025

Inspection Date 9/18/85

Please number comments to correspond with topics on previous page.

Discussion. Following observations were made:

(1) Culvert On The lower Pad Has Not Yet Been Extended.

Some tractor work had been completed to uncover a drainage so a culvert could be installed. No erosion and/or deposition problems were noted.

Operator stated the work would be done after equipment was freed from Trail Mtn.

(2) Some gravel like material needs to be cleaned from a ditch on the upper storage pad.

(3) The 1/2 round culvert between the middle & lower pad needs to be cleaned. No evidence could be found where the runoff had exited the 1/2 round culvert.

Road. The road from the gate to the mine was being watered.

Other Transportation facilities. The beltline that was the subject of NOV-89-26-18-1 was in the final stages of completion. Mr. Hansen stated he was under the impression that it would be operational on 9/19/89. The permanent rework has not been installed. The due date is 9/30/89. The operator was again reminded of the necessity to have this work completed.

Copy of report mailed to Gerald Hansen/C-Op.; Brian Sault/OSU; Joe Heltich/DOGM

Copy of report given to DFO

Inspector's signature Jm. J. Malenik

No. 26

WHITE - DOGM YELLOW - OSM PINK - PERMITTEE/OPERATOR GOLDENROD - NOV FILE

DOGM/IR-2

9/22/89

an equal opportunity employer

11/86 001049